

18th June, 1964

Last Service Letter issued for "Anglia" Range—No. 55—see Section: "Gearbox—Clutch".

DOOR TRIM PANEL



New "Anglia" Range

On all passenger cars the door trim panel is protected from interior damage and water seepage, by a plastic sheet fixed to the door inner frame with adhesive and tape.

Should this plastic sheet be removed at any time to carry out work on the door mechanisms, i.e. the door lock, window winder or hinges, etc., on completion of the repair, it must be replaced and securely attached with suitable adhesive.

Should this sheet become damaged during removal, it must be repaired or replaced with a new piece.

To avoid damage to the door trim panel it is vital to ensure that the plastic sheet is correctly positioned and properly sealed around the edges, paying special attention to the bottom edge.

Similar information to that contained in this Service Letter will also be issued in the following series:—

Service Letter No. 59 "Consul Cortina" Range

Service Letter No. 61 "Consul Corsair" Range

Service Letter No. 62 "Zephyr 4/6" and "Zodiac" Mk. III Range

Service Letter No. 60 "Consul 315" and "Capri" Range

The foregoing is for Dealer Information Only. Without exception all gratis repairs and replacements are subject to the current Warranty and Policy procedure.