

ANGLIA Range

(EXPORT)

19th June, 1964

Last Service Letter issued for "Anglia" Range — No. 58 — see Section: "Bodywork, Mudguards—Bonnet".

TEMPERATURE SENDER UNIT WASHER



New "Anglia" Range (with Temperature Gauge)

The washer fitted to the temperature gauge sender unit on assembly has been changed from a cork/fibre type to one manufactured from copper. This prevents the washer from being damaged during assembly.

When investigating water leaks in this area, the sealing effect of the washer should be determined. If suspect, the washer can be replaced by the current copper type.

Part Numbers are:—

- 113386-ES Former cork/fibre washer.
 - 112251-ES Current copper washer.
-

Similar information to that contained in this Service Letter will also be issued in the following series:—

- Service Letter No. 66 "Consul Cortina" Range*
 - Service Letter No. 65 "Consul Corsair" Range*
 - Service Letter No. 68 "Zephyr 4/6" and "Zodiac" Mk. III Range*
 - Service Letter No. 67 "Consul 315" and "Capri" Range*
 - Service Letter No. 43 "Thames" 5 and 7 cwt. Van Range*
-

The foregoing is for Dealer Information Only. Without exception all gratis repairs and replacements are subject to the current Warranty and Policy procedure.

No 64

PASSENGER CAR SERVICE LETTER 1964 series

ISSUED BY TECHNICAL PUBLICATIONS, Parts Sales and Service Operations

Ford Motor Company, Ltd. DAGENHAM, ESSEX.